



FEMB Status After Cooldown

20160203, 35t - B.Kirby

Overall Status



- All 16 FEMBs seem to be basically functioning after LAr filling
 - All FEMB links still working, no dead ASICs (!)
 - ADC synchronization needs to be redone with temperature stabilized
- Two FEMBs have no cooling related issues
 - RCE03 FEMB ADC sampling clock not working
 - RCE14 has an odd ADC synchronization issue, needs debugging
- Noise has increased after cooldown, $\sim 2000e^-$ ENC all channels
 - Need to track down exactly when noise jumped, preliminary observation looks like it was after boards were fully immersed (ie. after cooling and wires largely immersed)
 - Noise also significantly higher on induction plane wires following baseline setting change
 - Entirely correlated noise, in principle removable for non-zero suppressed data
 - Need to evaluate whether it makes sense to try setting all channels to 200mV baseline setting, would result in significantly less dynamic range for induction channels
- Plan initial set of noise measurements ASAP
 - Try to identify best (least noisy) settings for operation

ADC Synchronization During Cooldown



- During cooldown ADC ASICs regularly lost synchronization
 - Completely expected, but somewhat visible issue
 - Might consider fully automating ADC synchronization in future

Calibration Measurements During Cooldown



- Data-taking continued throughout cooldown
- In addition, every 30 minutes short pedestal + pulser runs taken to provide inputs to noise measurements
 - Used only one FE-ASIC gain + shaping time setting during entire cooldown, missed opportunity to test multiple configurations